

# SOUTHERN ANALYTICAL LABORATORIES, INC.

110 BAYVIEW BOULEVARD, OLDSMAR, FL 34677 813-855-1844 FAX 813-855-2218



Palm Island Estates Association  
PO Box 5244  
Grove City, FL 34224

August 4, 2015  
Work Order: 1507748

## Laboratory Report

Project Name		Surface Water Analyses							
Sample Description	Ferry Dock								
Matrix	Surface Water								
SAL Sample Number	1507748-01								
Date/Time Collected	08/03/15 09:18								
Collected by	Travis Wright								
Date/Time Received	08/03/15 14:17								
Parameters	Units	Results *	Method	PQL	MDL	Prepared	Analyzed	Dilution	
<b>Microbiology</b>									
Fecal Coliforms	CFU/100 ml	30	SM 9222D	1	1	08/03/15 15:49	08/04/15 13:58	1	

# SOUTHERN ANALYTICAL LABORATORIES, INC.

110 BAYVIEW BOULEVARD, OLDSMAR, FL 34677 813-655-1844 FAX 813-655-2218



Palm Island Estates Association  
PO Box 5244  
Grove City, FL 34224

August 4, 2015  
Work Order: 1507748

## Laboratory Report

Project Name		Surface Water Analyses							
Sample Description	Dock at Palm Dr.								
Matrix	Surface Water								
SAL Sample Number	1507748-02								
Date/Time Collected	08/03/15 09:30								
Collected by	Travis Wright								
Date/Time Received	08/03/15 14:17								
Parameters	Units	Results *	Method	PQL	MDL	Prepared	Analyzed	Dilution	
<b>Microbiology</b>									
Fecal Coliforms	CFU/100 ml	20	SM 9222D	1	1	08/03/15 15:49	08/04/15 13:58	1	

# SOUTHERN ANALYTICAL LABORATORIES, INC.

110 BAYVIEW BOULEVARD, OLDSMAR, FL 34677 813-855-1844 FAX 813-855-2218



Palm Island Estates Association  
PO Box 5244  
Grove City, FL 34224

August 4, 2015  
Work Order: 1507748

## Laboratory Report

Project Name		Surface Water Analyses						
Sample Description	71 Tarpon Way							
Matrix	Surface Water							
SAL Sample Number	1507748-03							
Date/Time Collected	08/03/15 09:38							
Collected by	Travis Wright							
Date/Time Received	08/03/15 14:17							
Parameters	Units	Results *	Method	PQL	MDL	Prepared	Analyzed	Dilution
<b>Microbiology</b>								
Fecal Coliforms	CFU/100 ml	10	SM 9222D	1	1	08/03/15 15:49	08/04/15 13:58	1

# SOUTHERN ANALYTICAL LABORATORIES, INC.

110 BAYVIEW BOULEVARD, OLDSMAR, FL 34677 813-855-1844 FAX 813-855-2218



Palm Island Estates Association  
PO Box 5244  
Grove City, FL 34224

August 4, 2015  
Work Order: 1507748

## Laboratory Report

Project Name		Surface Water Analyses						
Sample Description	Island House							
Matrix	Surface Water							
SAL Sample Number	1507748-04							
Date/Time Collected	08/03/15 09:46							
Collected by	Travis Wright							
Date/Time Received	08/03/15 14:17							
Parameters	Units	Results *	Method	PQL	MDL	Prepared	Analyzed	Dilution
<b>Microbiology</b>								
Fecal Coliforms	CFU/100 ml	220	SM 9222D	1	1	08/03/15 15:49	08/04/15 13:58	1

# SOUTHERN ANALYTICAL LABORATORIES, INC.

110 BAYVIEW BOULEVARD, OLDSMAR, FL 34677 813-855-1844 FAX 813-855-2218



Palm Island Estates Association  
PO Box 5244  
Grove City, FL 34224

August 4, 2015  
Work Order: 1507748

## Laboratory Report

Project Name		Surface Water Analyses						
Sample Description	Boyer Lagoon							
Matrix	Surface Water							
SAL Sample Number	1507748-05							
Date/Time Collected	08/03/15 09:57							
Collected by	Travis Wright							
Date/Time Received	08/03/15 14:17							
Parameters	Units	Results *	Method	PQL	MDL	Prepared	Analyzed	Dilution
<b>Microbiology</b>								
Fecal Coliforms	CFU/100 ml	1 U	SM 9222D	1	1	08/03/15 15:49	08/04/15 13:58	1

# SOUTHERN ANALYTICAL LABORATORIES, INC.

110 BAYVIEW BOULEVARD, OLDSMAR, FL 34677 813.855.1844 FAX 813.855.2218



Palm Island Estates Association  
PO Box 5244  
Grove City, FL 34224

August 4, 2015  
Work Order: 1507748

## Laboratory Report

Project Name		Surface Water Analyses						
Sample Description	Resort Entrance							
Matrix	Surface Water							
SAL Sample Number	1507748-06							
Date/Time Collected	08/03/15 10:09							
Collected by	Travis Wright							
Date/Time Received	08/03/15 14:17							
Parameters	Units	Results *	Method	PQL	MDL	Prepared	Analyzed	Dilution
<b>Microbiology</b>								
Fecal Coliforms	CFU/100 ml	1 U	SM 9222D	1	1	08/03/15 15:49	08/04/15 13:58	1

# SOUTHERN ANALYTICAL LABORATORIES, INC.

110 BAYVIEW BOULEVARD, OLD SMAR, FL 34677 813.855.1844 FAX 813.855.3218



Palm Island Estates Association  
PO Box 5244  
Grove City, FL 34224

August 4, 2015  
Work Order: 1507748

## Laboratory Report

Project Name		Surface Water Analyses						
Sample Description	Colony Unit							
Matrix	Surface Water							
SAL Sample Number	1507748-07							
Date/Time Collected	08/03/15 10:27							
Collected by	Travis Wright							
Date/Time Received	08/03/15 14:17							
Parameters	Units	Results *	Method	PQL	MDL	Prepared	Analyzed	Dilution
<b>Microbiology</b>								
Fecal Coliforms	CFU/100 ml	20	SM 9222D	1	1	08/03/15 15:49	08/04/15 13:58	1

# SOUTHERN ANALYTICAL LABORATORIES, INC.

110 BAYVIEW BOULEVARD, OLDSMAR, FL 34677 B13-855-1844 FAX B13-855-2218



Palm Island Estates Association  
PO Box 5244  
Grove City, FL 34224

August 4, 2015  
Work Order: 1507748

## Laboratory Report

Project Name		Surface Water Analyses						
Sample Description	Bocilla Lagoon							
Matrix	Surface Water							
SAL Sample Number	1507748-08							
Date/Time Collected	08/03/15 10:36							
Collected by	Travis Wright							
Date/Time Received	08/03/15 14:17							
Parameters	Units	Results *	Method	PQL	MDL	Prepared	Analyzed	Dilution
<b>Microbiology</b>								
Fecal Coliforms	CFU/100 ml	1 U	SM 9222D	1	1	08/03/15 15:49	08/04/15 13:58	1



# SOUTHERN ANALYTICAL LABORATORIES, INC.

110 BAYVIEW BOULEVARD, OLDSMAR, FL 34677 813-855-1844 FAX 813-855-2218



Palm Island Estates Association  
PO Box 5244  
Grove City, FL 34224

August 4, 2015  
Work Order: 1507748

## Laboratory Report

Project Name		Surface Water Analyses						
Sample Description	Kettle Harbor							
Matrix	Surface Water							
SAL Sample Number	1507748-09							
Date/Time Collected	08/03/15 10:46							
Collected by	Travis Wright							
Date/Time Received	08/03/15 14:17							
Parameters	Units	Results *	Method	PQL	MDL	Prepared	Analyzed	Dilution
<b>Microbiology</b>								
Fecal Coliforms	CFU/100 ml	1 U	SM 9222D	1	1	08/03/15 15:49	08/04/15 13:58	1

# SOUTHERN ANALYTICAL LABORATORIES, INC.

110 BAYVIEW BOULEVARD, OLDSMAR, FL 34677 B13-855-1844 FAX 813-855-2218



Palm Island Estates Association  
PO Box 5244  
Grove City, FL 34224

August 4, 2015  
Work Order: 1507748

## Laboratory Report

Project Name		Surface Water Analyses						
Sample Description	Kettle Harbor Drive							
Matrix	Surface Water							
SAL Sample Number	1507748-10							
Date/Time Collected	08/03/15 11:07							
Collected by	Travis Wright							
Date/Time Received	08/03/15 14:17							
Parameters	Units	Results *	Method	PQL	MDL	Prepared	Analyzed	Dilution
<b>Microbiology</b>								
Fecal Coliforms	CFU/100 ml	1 u	SM 9222D	1	1	08/03/15 15:49	08/04/15 13:58	1

# SOUTHERN ANALYTICAL LABORATORIES, INC.

110 BAYVIEW BOULEVARD, OLDSMAR, FL 34677 B13-855-1844 FAX 813-855-2218



Palm Island Estates Association  
PO Box 5244  
Grove City, FL 34224

August 4, 2015  
Work Order: 1507748

## Laboratory Report

Project Name		Surface Water Analyses						
Sample Description	Beach Place Lagoon							
Matrix	Surface Water							
SAL Sample Number	1507748-11							
Date/Time Collected	08/03/15 10:19							
Collected by	Travis Wright							
Date/Time Received	08/03/15 14:17							
Parameters	Units	Results *	Method	PQL	MDL	Prepared	Analyzed	Dilution
<b>Microbiology</b>								
Fecal Coliforms	CFU/100 ml	10	SM 9220	1	1	08/03/15 15:49	08/04/15 13:58	1

# SOUTHERN ANALYTICAL LABORATORIES, INC.

110 BAYVIEW BOULEVARD, OLDSMAR, FL 34677 (813) 855-1844 FAX (813) 855-2218



Palm Island Estates Association  
PO Box 5244  
Grove City, FL 34224

August 4, 2015  
Work Order: 1507748

## \* Qualifiers, Notes and Definitions

---

Results followed by a "U" indicate that the sample was analyzed but the compound was not detected. Results followed by "I" indicate that the reported value is between the laboratory method detection limit and the laboratory practical quantitation limit.

A statement of estimated uncertainty of test results is available upon request.

For methods marked with \*\*, all QC criteria have been met for this method which is equivalent to a SAL certified method.

Test results in this report meet all the requirements of the NELAC standards. Any applicable qualifiers are shown below.

Questions regarding this report should be directed to :

Kathryn Nordmark

Telephone (813) 855-1844 FAX (813) 855-2218

Kathryn@southernanalyticalabs.com

A handwritten signature in black ink, appearing to read "Francis I. Daniels".

---

Florida Certification Number: EB4129

NELAP Accredited

Francis I. Daniels, Laboratory Director  
Leslie C. Boardman, Q.A. Manager